(512) 347-9030

1/4





FIG. 1

(512) 347-9030

2/4



PORTION OF TILE Z BUFFER 122

220	NEAR	NEAR	
220	FAR	FAR	224
	BGNEAR	BGNEAR	
	BGFAR	BGFAR	1
	FLAGS	FLAGS	

FIG. 2

SHEET 3/4

(512) 347-9030

3/4




FIG. 3

The state of the s

ATTY. DOCKET No.: 1001-0180

(512) 347-9030

4/4




FIG. 4